Lake Ngāpōuri / Opōuri



INFOSHEET 13, DECEMBER 2017

This information sheet has been prepared for Te Arawa whānau to summarise information about:

- research and monitoring occurring on Lake Ngāpōuri / Opōuri.
- projects occurring on, and adjacent to Lake Lake Ngāpōuri / Opōuri, particularly efforts to reduce the impacts of land use on lake water quality.

It will be reviewed and updated annually.


Lake Ngāpōuri / Opōuri is a 19ha volcanic lake located in Waikite Valley, west of the Waiotapu Thermal Area. It is a tributary of the Opōuri Stream, Waiotapu River and Waikato River.

WATER QUALITY MONITORING

The condition of the three Te Arawa Lakes within the Waikato Region, including Lake Ngāpōuri, are assessed using the Submerged Plant Indicator or SPI. This looks at the amount of native and invasive plants and assigns a score – the higher the SPI, the better the water quality.

WATER QUALITY TREND

The water quality within Lake Ngāpōuri has indicated moderate to high ecological health over the last 30 years. The LakeSPI has dropped since 2004, owing to a greater percentage of invasive lake weed.





3 LAKES ACTION PLAN

The 3 Lakes Action Plan seeks to protect, enhance and restore Lakes Ngāpōuri, Tutaeinanga and Ngāpōuri. It involves an interagency approach, is led by Ngāti Tahu-Ngāti Whaoa Runanga Trust and funded by the Waikato River Authority.

ACTION PLAN PROJECTS

Includes, but is not limited to:

Project	Status
Lakes Tutaeinanga and Ngāpouri	In Progress
Riparian Restoration - led by Ngāti	
Tahu-Ngāti Whaoa Runanga Trust and	
funded by the Waikato River Authority.	

RESEARCH

Research	Findings	
NIWA Taonga Fish species, 2007	 Kākahi were present. Historical and current status of kōaro unknown. As a tributary of the Waikato River, Lake Ngāpōuri may be most suitable for stocking of elvers (tuna restoration). 	
Tau kõura Monitoring 2017	 No koura captured in this survey. Common bullies were abundant. 	